

Existing Site Condition Photographs
Application for Regulated Wetlands Activity
Fintech Village, LLC
School of Social Work Building
Demolition, Erosion & Sedimentation Control & Soil Remediation
1800 Asylum Avenue
West Hartford, Connecticut
DPI Project No. 2815.B
Taken September 10, 2019 by Bestech, Inc.

The following photographs were taken of the preparation of the membrane used to contain contaminated soils and hardscape elements until the removal and remediation process begins. These photographs were taken after those documented on the May 1, 2019 site plan set appended to the Eagle Environmental, Inc. PCB Cleanup and Disposal Plan. The east side of the building is featured as an example.



